


Mercedes ACM 2.1 Euro 6 Adblue Control ECU

Repair service available on this product.



ACM 2/2.1 Euro 6 Adblue Control ECU Repair

A0004463154, A0004463954, A0004464054,
A0004464854, A0004466754, A0004463454 etc.

Common faults & services: Complete failure, CAN link to Adblue doser unit failure, damaged connectors, water damage, CAT/DPF temperature sensor faults, lower power supply & NOX sensor faults, reprogramming, immobiliser removal.

We repair your unit so no need for reprogramming, you can simply refit the ECU back on to the vehicle when you receive it back.

- Collections of items to be repaired or refurbished are free of charge.
- Testing and technical support is available by contacting our office.

**CLICK TO SEE OUR
FULL RANGE**